

| | |
|--------------|-------------|
| Bulletin No. | P_05_2022 |
| Date | August 2022 |

F45s / F80s

Dear customer,

we would like to inform you that for F45s and F80s awnings with a packaging label (blue) between 22178108 and 22195108 if the situation as per drawing A occurs (screw short in relation to nut) it is advisable to replace the nylon washer (indicated in yellow in the drawing) with the one from kit 98673-279 available free of charge.

This operation is recommended to restore the correct tightening of the nut as per the drawing.

