

Bulletin No.	P_03_2021
Date	May 2021

Vent 28 F / Turbo Vent 28 F

Dear customer,

during the installation of the product Vent 28 F / Turbo Vent 28 F

**Item No. 07902-01-
Item No. 07902-01B
Item No. C7902-01-
Item No. C7902-01B
Item No. C7902A01-
Item No. C7902A01B
Item No. C7902-02B**

in order to prevent any water infiltration, remember to seal the underside of the outer frame well for a minimum width of 10 mm, following the appropriate tracks, especially at the points where there are the 2 plastic joints (as shown in the pictures on the right).

Recommended sealant:
SIKALASTOMER-710 / THEROSTAT II
(or other butyl sealant)

Never remove the plastic joints from their seats.

